

# BD-7150 Manual Supplement

BD7150-01A-E

Before building, please familiarize yourself with the instructions in the main manual and the manual supplement. Pay special attention to the revised instructions before building.

The contents are changed. Please check the contents indicated in the following.

The turnbuckle of the kit accessory is changed made of the titanium.

See instructions on page 10

Special servo mount included.  
Refer to page 10 assembled.

See instructions on page 12

Double Joint Front Universal Driveshaft included.  
Assembly, refer to the illustrations.

